



## 2000 FALCON 900EX

S/N 71      REG# N110EX

### AIRCRAFT HIGHLIGHTS

- One Owner Since New
- MSP Gold
- Direct TV

#### TRIPLE S AVIATION

4570 Westgrove Drive  
Suite 240  
Addison, Texas 75001  
USA


Dubai Airport Free Zone  
Suite 4WB-649  
Dubai International Airport  
Dubai, U.A.E

USA mobile: +1.214.704.9282  
UAE mobile: +971.05.8955.962

Istuder@triplesaviation.com  
www.triplesaviation.com

#### JACK PREWITT & ASSOCIATES

Josh Pitts  
USA Cell: +1 817 988 0158  
USA Office: +1 817 283 2826  
Email: jpitts@jackprewitt.com  
www.jackprewitt.com



TRIPLE S AVIATION

4570 Westgrove Drive  
Suite 240  
Addison, Texas 75001  
USA

Dubai Airport Free Zone  
Suite 4WB-649  
Dubai International Airport  
Dubai, U.A.E

USA mobile: +1.214.704.9282  
UAE mobile: +971.05.8955.962

Istuder@triplesaviation.com  
www.triplesaviation.com

JACK PREWITT & ASSOCIATES

Josh Pitts  
USA Cell: +1 817 988 0158  
USA Office: +1 817 283 2826  
Email: jpitts@jackprewitt.com  
www.jackprewitt.com

**AIRCRAFT TOTAL TIME:**

2588.7

**LANDINGS:**

1118

**ENGINES:**

MSP GOLD

Engine 1-2488.5 Hrs....1084 cycles....MPI C/W

Engine 2-2447.4 Hrs....1067 cycles....MPI C/W

Engine 3-2433 Hrs....1058 cycles....MPI C/W

"C" Inspection C/W November 13 2006 @ 1672.7 Hours

APU

MSP

Garrett GTCP 36-150F 1516hrs

**AVIONICS:**

Honeywell Primus 2000 5-Tube Electronic Flight Display System/Integrated Avionic Suite

Triple FMZ-2000 Flight Management System - with Dual GPS

Triple Collins VHF-422C COMM's

Dual Collins VIR-432 NAV's

Dual Collins DME-442 DME's

Dual Collins ADF-462 ADF's

Dual Collins TDR-422 Transponders (Mode S) Enhanced Surveillance

Collins TCAS 94 (TCAS 94) Change 7

Honeywell MK-V Enhanced GPWS System - with Windshear Detection

Honeywell Primus 880 Color Weather Radar - with Dual Controllers

Dual Honeywell AA-300 Radio Altimeter System

Dual Collins HF-9000 Communications System/Selcal

Dual Channel

Magnastar C-2000 Digital Flitephone - with Cabin PBX

Honeywell Cockpit Voice Recorder

Honeywell Flight Data Recorder

Airshow Genesys Network Entertainment Display  
Flight Dynamics HGS-2860 Heads Up Display (Cat III Capable)

Direct TV -Dual Channel Airshow 931-(US and Europe)

SATCOM Aero I Sextant JetSat

Honeywell SAT-AFIS Satellite Data Communications

Socata Tri-Frequency Emergency Locator 406 Mhz

ELT

Aircraft Total Time 2588.7

Landings 1118

**INTERIOR:**

14 passenger

Forward Jumpseat Forward Crew lav Forward RH

Galley LH Auxiliary Galley/Entertainment Cabinet

Forward Cabin LH/RH 2 place Club Mid Cabin 4 Place

Club opposite Multi-Purpose Storage Cabinets Aft

Cabin Dual 3 place Divans Aft Lav

Partial window liners and carpet replaced November 2006

**EXTERIOR:**

Overall White with Fighter Blue/ Misty Blue stripes  
Original paint

Maintenance Status ACTT 2588.7 Hrs. Landings 1118

A Inspection c/w October 15, 2008-

2A Inspection c/w April 20, 2008-

3A Inspection c/w October 15 2008

A+ Inspection c/w October 15 2008

2A+ Inspection c/w April 20 2008

3A+ Inspection c/w October 15 2008

4A+ Inspection c/w November 13 2006

B Inspection c/w November 13 2006@1672 hrs

All Maintenance C/W thru September 09